

EXHIBIT D

LESSOR'S WORK

1. Replacement of four main electrical automatic transfer switches related to emergency power.
2. Branch Circuit corrections within the electrical service infrastructure (see attached electrical assessment report dated 5/17/16).
3. Scullery grease interceptor installation (main kitchen)

Exhibit D