


U.S. SURVEY NO. 12410


Lot 13



Recovered a metal rod, set flush with the rock in a drill hole, with no cap, from which

Reference monuments of record exist and are in good condition.


Monument is located on the top of a steep rock ledge a few feet above the line of mean high tide. There is a navigational aid within a few feet of the marker and sitting on top of the NW RM.



Recovered a Stainless Steel Post, 2 1/2 in., diam., with a 3 I/4 in. Brass Cap, Marked as Shown, set flush with rocks, from which

Bearing trees of record are alive in good condition. BT's were not measured due to a steep slope and extensive clearing to make measurement possible. However, bearings were in agreement with record.


SW 21" Spruce, with illegible scribe marks NW 20" Hemlock, mkd. X BT



Recovered a Stainless Steel Post, 2 1/2 in., diam., with a 3 I/4 in. Brass Cap, Marked as Shown, projecting 3 ins. out of the ground, from which the original bearing trees

A cedar, 18 ins. diam., bears N. 27° E., 21.32 ft. dist., with no legible scribe marks. (Record: N. 32 I/4° E., 21.10 ft.)

A spruce, 7 ins. diam., bears S. 71° E., 13.7 ft. dist., with no legible scribe marks. (Record: S. 62 I/4° E., I3.85 ft.)



Recovered a Bronze Disk, Marked as Shown set in bedrock on a point just below navigation aid, from which

Reference monuments of record were located and are in good condition.

05


Subdivision\DWG\Nak

Sound

Found NGS FAT - an X in white lead at top of steep rock, from which

One of two Reference monuments of record were located. Other not found due to safety hazard.


The monument location was not suitable for instrument




Recovered a Bronze Disk, Marked as Shown set in bedrock on a rocky point, from which

Reference monuments of record were located and in good condition.

TYPICAL SET PRIMARY MONUMENT



Set a 3 1/4" Aluminum Cap on a 2 1/2" Aluminum Post, 30" Long, 24" in the ground with a Magnet in an Orange Plastic case at the base of the Monument Carsonite Witness Post to the North TYPICAL SET SECONDARY MONUMENT



ANCHORAGE, ALASKA ALASKA STATE LAND SURVEY NO. 2015-06

DEPARTMENT OF NATURAL RESOURCES DIVISION OF MINING, LAND & WATER

STATE OF ALASKA

Beginning: August 6, 2015
Ending: August xx, 2016

Beginning: August xx, 2016

August xx, 2016

Anchorage, Alaska 99503

DATE OF SURVEY

Lindsey S. Vaughan, RLS

NAKWASINA SOUND SUBDIVISION

A SUBDIVISION OF PORTIONS OF SW 1/4 UNSURVEYED SECTION 28, AND NW 1/4, W 1/2 NE 1/4, & NW 1/4 SE 1/4, UNSURVEYED SECTION 33, FRACTIONAL TOWNSHIP 54 SOUTH, RANGE 63 EAST COPPER RIVER MERIDIAN, ALASKA CREATING LOTS 1-18 AND TRACT A CONTAINING 122.35 ACRES MORE OR LESS

LOCATED WITHIN SITKA RECORDING DISTRICT

DRAWN BY: JCG APPROVAL RECOMMENDED DATE: \_\_\_\_\_\_12/2015 STATEWIDE PLATTING SUPERVISOR DATE DNR FILE NO. SCALE:

1"= 100' L.S.V.

SHEET 4 OF 4

ASLS 20150006